



FIG. 1

P E JC119
 NOV 26 2003
 TRADEMARK OFFICE




Channel Control byte (CCNTRL) 237

Reserved	Soft Flag1	Soft Flag0	Command Completions Status
7	6	5	4 3 2 1 0


Command Completion Status

0	Reserved / Unused Channel
1	Completed with No Errors
2	Zero bytes in "Transfer size" field in CCD (LM Only)
3	Zero bytes in "Segment size" field in FD
4	PCI Frame Overrun
5	LM Frame Overrun
6	Reserved
7	PCI Abort Error during transfer
8	PCI Parity Error during transfer (PCI Read Only)
9-F	Reserved

FIG. 2



PTI Data Descriptors



PTI Chanel Control byte (PTI CCNTRL)

IRQ per Seg	Dump Data	Soft Flag1	Soft Flag0	Command Completions Status			
7	6	5	4	3	2	1	0

Command Completion Status

0	Reserved / Unused Channel
1	Completed with No Errors
2	Zero bytes in "Transfer size" field in CCD (LM Only)
3	Zero bytes in "Segment size" field in FD
4	PCI Frame Overrun
5	LM Frame Overrun
6	Unit Start Indicator detected
7	PCI Abort Error during transfer
8	PCI Parity Error during transfer (PCI Read Only)
9-F	Reserved

FIG. 3